



Search All Scott Simmons, search your mailbox

Search Mail

Search Web

Home

Scott



Compose

Search results Archive Move Delete Spam More



Inbox

Drafts (112)

Sent

Archive

Spam (125)

Trash (781)

Smart Views

Folders (13)

gas station site

PCS (13)

village resort

Recent

Property Enquiry: 121 Quebec Drive

Minimum water service required for subdivision:							
Adequate supply of potable water	♦	♦	♦	♦	♦	♦	
Minimum sewage service required for subdivision:							
Individual on-site sewage treatment system per lot	♦	♦	♦	♦	♦	♦	♦
Minimum average area of lots in a subdivision (ha)	2	8	32	2.8	4	12	
Minimum area of an individual lot that may be created through subdivision, provided there is an individual on-site sewage treatment system per lot and an adequate supply of potable water (ha)	0.6	0.6	32	2	4	12	♦
Minimum area of an individual lot that may be created through subdivision where there is an individual on-site sewage treatment system per lot and a community water system (ha)	0.4	0.6	32	2	4	12	2
Minimum area of an individual lot that may be created through subdivision where there is a community sewage collection system and a	0.4	0.6	32	2	4	12	0.6

Try the new Yahoo Mail